

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

KB1393
North
> 1
1.759 mi.
9287 ft.

SPILL NUMBER 9904293
40-14 QUENTIN RD
BROOKLYN, NY

Site 1 of 2 in cluster KB

NY Spills S104649345
N/A

Relative:
Higher

Actual:
19 ft.

SPILLS:

Name: SPILL NUMBER 9904293
Address: 40-14 QUENTIN RD
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9904293 / 1999-10-20
Facility ID: 9904293
Facility Type: ER
DER Facility ID: 252347
Site ID: 312976
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1999-07-12
Investigator: JHOCONE
Referred To: Not reported
Reported to Dept: 1999-07-12
CID: 312
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-07-12
Spill Record Last Update: 2000-06-05
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS NOTES Aerial joint leak in front of 40-14 Quentin Rd. Between pole#2211 and pole#2210. He found 15 drops of oil covering a 2'x2' area on concrete sidewalk. Has stated no sewers or waterways are affected. No shrubbery or cars were affected either.

Pigs have been placed and the area roped off. Joint was wrapped in a plastic bag. Crew standing by. Update Sample will be cancelled and cleanup done a 50-499ppm as per B. Donovan 7-12-99 There is approx. a 2'x4' stain half on driveway apron and half on lawn of 4018 Quentin Rd. Homeowners name is Ed Coppola 1-12-99 1345hrs onsumer was advised to have sod on lawn replaced and submit bill to Robert Carroll - 30 Flatbush 15:05 hrs Removed 2'x4' square of lawn, double-washed driveway apron, cleanup completed. Consumer requested company install the new sod. Picked up 2 squares of sod and installed same. Customer satisfied & no further action required."
"15 DROPS TO CONCRETE FROM A CABLE JOINT - WILL CLEAN UP AS 50-499PPM - CASE #126362"

Remarks:

All Materials:
Site ID:

312976

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 1078728
Operable Unit: 01
Material ID: 304181
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported